Security Storage Service, Inc.

4901 Fremont Rd Nixa MO 65714

417-725-4611

October 10, 2018

TO: City of Springfield

Dear Sirs:

Pursuant to our agreement and instructions, an asbestos inspection of a commercial structure located at 2104 National, Springfield, Missouri, was completed on October 2, 2018. The inspector was Keith Mills, Certificate #7034121217MOIR7058. The inspection included observation and bulk sampling, as necessary, of areas and materials suspected to have asbestos content. Any samples taken are referred to San Air Laboratories, a nationally accredited laboratory, for analysis. Chain of custody documentation is preserved.

Observation and sampling are limited to areas of the property, which are visible and accessible during normal usage of the structure. Should additional areas or materials, which might be suspect, become exposed during demolition, renovation, or alteration, we will return to inspect these as desired.

Of the materials surveyed and/or tested on the original inspection date, (One sample tested Positive for asbestos).

This assessment was conducted by an AHERA and Missouri certified asbestos inspector. Conclusions contained herein are based solely upon the described scope of work in Security Storage Service's proposal and inspection of the described areas. No opinion, expressed or implied, is made as to the presence or absence of asbestos in areas of the site not accessible and/or not included in the scope of this inspection. There are many situations where ACM may be concealed in inaccessible areas. When these areas become exposed during construction, remodeling, or demolition, such materials should either be sampled or treated as assumed asbestos-containing. Further inspection may be warranted as areas are exposed during such activities. This report has been prepared for the client designated above and is not for use of other parties without the express consent of that client.

Security Storage Service, Inc.

October 10, 2018

SAMPLING CHECKLIST

Location: 2104 N. National, Springfield, MO

Date: October 2, 2018 Client: City of Springfield

Exterior Description: Rolled Roof, Block Walls

Interior Description: Wood ceiling and walls, Tile and Concrete floor

The following samples were taken to determine the presence of asbestos:

100214 Floor Tile North room 300 ft POSIT 100215 Ceiling Tile North room 300 ft Negati 100216 Sheetrock Entry 400 ft Negati	ive

Keith Mills

Security Storage Service

Kent Mill